

BALDWIN COUNTY

HIGHWAY DEPARTMENT P.O. Box 220 SILVERHILL, ALABAMA 36576

TELEPHONE: (251) 937-0371 FAX (251) 937-0201 CAL MARKERT, P.E. COUNTY ENGINEER

Baldwin County Utility Contacts

AT&T

Jeff Hadley - 251-626-2913

Baldwin County Fiber

Mike Job - 251-937- 0343

Baldwin County Sewer

Richie Barnett - (Supervisor) - 251-971-6047 Ryne Engel - (Field Tech) - 251-284-2122

Belforest Water

Steve (Supervisor) - 251-709-0176

Century Link

Robin Rockstall – 251-952-5279 Kenny Kaiser – 251-952-5788 Forest Cherney– 251-952-5286

East Central Water

Ryan Frolik (Supervisor) – 251-747-7478

EMC

Johnny Brinkman – 251-510-1483 Mark Creamer – 251-989-0126

City of Fairhope

Dan McCrory (Supervisor-water and sewer) - 251-990-0120 Jay Whitman (Water/Sewer) - 251-990-0170 Robert Rohm (Gas) - 251-928-8003

Harbor Communications

Troy Sablich - 251-583-0304

Level 3 Fiber

Brett Deslonde - 251-978-5280

Town of Loxley

Richard Rider (Supervisor) - 261-964-7644

Mediacom

Tobias Eringman – 251-370-4037 Bill Huggins – 850-698-2314

Perdido Bay Water

Bruce Hartman (Water) - 251-987-5816

Riviera

Leon Barber (Power-Foley) – 251-370-5075 Gary Richmond (Water) -251-943-5001 Danny Scott (Gas) – 251-970-4127

City of Robertsdale

Greg Smith (Engineer) – 251-947-8955 David Kilcrease (Supervisor) – 251-947-6005

Southern Light

John Hixon – 251-370-2085 Jennifer Johnson -251-445-1687



BALDWIN COUNTY

HIGHWAY DEPARTMENT P.O. Box 220 SILVERHILL, ALABAMA 36576

TELEPHONE: (251) 937-0371 Fax (251) 937-0201

CAL MARKERT, P.E. **COUNTY ENGINEER**

Utility Information for: BCP# 0218114 (Hutchinson, Moore & Rauch LLC)

Culvert Restorations

Statement: The following information should only be used for informational purposes; utilities shall be checked by the contractor on site to verify current site conditions. The following information was compiled to the best of our knowledge but it is the responsibility of the contractor to determine actual conditions.

Color Guide:

Green sites have no known utility conflicts

Yellow sites have not yet been determined

Red sites have known utility conflicts

BC200-136 (CR 85)

East Central Water - They say their water line should be ok.

No sewer lines at this site

CenturyLink - Has not confirmed a definite conflict. They say they have a 100 pair cable in stock if it's damaged.

BC200-150 (Ard Rd)

East Central Water -They say their water lines should be ok.

No sewer lines at this site

Century Link - They have not confirmed a definite conflict. They say they have a 25 pair cable in stock if it's damaged.

BC200-174 (Vaughn Rd)

East Central Water -They say their water lines should be ok.

No sewer lines at this site.

Century Link - They have not confirmed a definite conflict. They say they have a 50 pair cable in stock if it's damaged.

BC200-187 (CR 38)

0 East Central Baldwin Water – they have a 10 "water line on top of the existing 48" pipe. They are proposing to shut the pressure off and work with the contractor to slide the new pipe under the waterline.

0 CenturyLink - has a fiber cable at this site, conflict not determined.

BC300-213 (Kichler Circle North)

East Central Baldwin Water - they have a 6" water line on this site, they say it should not be in conflict. Riviera utilities (Gas) - Danny Scott said they have a 2"PE gas line 6' deep and it's under the culvert. He said it should not be a conflict because of the depth.

0 Century Link – they say they have a 50 pair on the north side and a 6 pair on the south side but it is not known if it will be a conflict.

BC300-001 (CR 83)

- East Central Baldwin Water they have a 6" water line on this site, they say it shouldn't be a conflict.
- CenturyLink has a fiber cable on the east side of the road at this location but it is not known if it will be a conflict.

BC300-179 (CR 93)

- Riviera Power They ask that we give them the start date as soon as possible so they can shut off the power.

 Riviera will need to send notices out as soon as possible.
- Perdido Bay Water They have a water line on the east side of the road 3 or 4 feet from the end of the existing drain pipe. They say the water line should not be in conflict with the proposed culvert.
- O CenturyLink has a copper cable on the west side of the road, conflict not determined.

BC300-210 (Kichler Circle West)

- Riviera Utilities Gas Riviera said they have a 2"PE gas line 4' deep 3' outside of the culvert in the ditch. Riviera does not think this will be in conflict.
- CenturyLink has a copper cable on the west side of the road, conflict not determined.

BC300-229 (Kleinschmidt Road)

- East Central Baldwin Water They have a water line on the south side of the road. They shot the elevation and it will not be a conflict.
- CenturyLink has a copper cable at this site, conflict not determined.

BC300-358 (Malkoskie Road)

CenturyLink - has a copper cable at this site, conflict not determined.

BC300-359 (CR 34)

- East Central Baldwin Water they have a 6" water line on top of the existing pipe. They are proposing to shut the pressure off and work with the contractor to slide the new pipe under the waterline.
- Century Link Says they are clear.

BC300-377 (CR 36)

- East Central Baldwin Water they have a water line at the site, they say no conflict.
- Baldwin County Sewer Ryne Engle said they have a 10" sewer under this drain pipe. Ryne said they bored under the pipe and he does not think there's a conflict.
- CenturyLink has a copper cable at this site, conflict not determined.

BC300-392 (Gean Rd)

- East Central Baldwin Water they have a 3" line on top of the existing drain pipe. They are proposing to shut the pressure off and work with the contractor to slide the new pipe under the waterline.
- O CenturyLink has a copper cable at this site, conflict not determined.

BC300-049 (Woerner Rd)

- East Central Baldwin Water –they have a water line on site, they say it should not be in conflict.
- CenturyLink has a copper cable at this site, conflict not determined.

BC300-022 (Woodland Lane)

- Perdido Bay Water Bruce Hartman said they have a water line on site, he says it should not be a conflict.
- CenturyLink has a copper cable on site, conflict not determined.